

IMMEDIATE ACTION

Overhead Heaters

February 16, 2017

WHAT and WHY

A recent incident involving overhead heaters could have resulted in serious injury and/or major property damage. All overhead heaters must be visually inspected to ensure: 1. Thermostats are in good condition and working properly 2. There are no rusted heating tubes; and 3. None of the heating tubes exhibit bending. Even if you don't have heaters at your location, you are still required to complete the heater survey.

ACTION

IMMEDIATELY

 Check the thermostat for each unit for damage or improper function



 Check for rusted heating tubes (see the example in the photo to the right)

**IF A RUSTED HEATING TUBE IS IDENTIFIED OF A TUBE IS SEPARATED FROM ITS COUPLING, CONTACT MAINTENANCE TO HAVE THAT UNIT REMOVED FROM SERVICE (LOCK OUT/TAG OUT).

 Ensure the heating tubes are set "flush" into the couplings with no evidence of bending



Published on: 02/15/17 ver 1.0



DELIVERABLES

Complete the "Final Step" below

FINAL STEP

Complete the following **Heater Survey**

Please complete the above survey within 24 hours from the time of receiving this message.

"We do this together!"